


# SUNSET HILL



## BUILDING LIMITATIONS



## SPACE NEEDS

- \_group rooms
- \_community room
- \_public restroom at office

## FACILITIES LIMITATIONS

- \_settling foundations cause water to leak into the school
- \_classrooms lack electrical outlets and telecommunications infrastructure
- \_HVAC system needs to be updated with more control for individual rooms, and to limit noise levels in learning environments
- \_restrooms need to be outfitted with automatic fixtures
- \_teachers and staff need more control over light levels in classrooms


## SITE LIMITATIONS

LOT: 7.69 acres

HARD PLAYGROUND: 0.29 acres

SOFT PLAYGROUND: 0.35 acres

FIELDS: 3.35 acres



pick-up at the end of the school day causes congestion of cars along 9th St. and Schwartz Rd.


primary and intermediary grades share playground equipment

## POTENTIAL IMPROVEMENTS

PRIORITY 1: REPLACEMENT OF PORTABLES AND SHARED GYM AND CAFETERIA



PRIORITY 2: INCREASE OF SQUARE FOOTAGE TO MATCH THE UPPER RANGE IN THE DISTRICT



PRIORITY 3: INCREASE OF SQUARE FOOTAGE TO MEET NATIONWIDE STANDARDS FOR NEW CONSTRUCTION

